# Energy performance certificate (EPC)

1, Kingsdale Park
BELFAST
BT5 7BY

Energy rating
Valid until: 6 November 2028

Certificate number: 0139-3996-0209-7808-2934

### Property type

Ground-floor flat


#### **Total floor area**

76 square metres

### Energy efficiency rating for this property

This property's current energy rating is D. It has the potential to be C.

See how to improve this property's energy performance.



The graph shows this property's current and potential energy efficiency.

Properties are given a rating from A (most efficient) to G (least efficient).

Properties are also given a score. The higher the number the lower your fuel bills are likely to be.

For properties in Northern Ireland:

- the average energy rating is D
- the average energy score is 60

### Breakdown of property's energy performance

This section shows the energy performance for features of this property. The assessment does not consider the condition of a feature and how well it is working.

Each feature is assessed as one of the following:

- · very good (most efficient)
- good
- average
- poor
- very poor (least efficient)

When the description says "assumed", it means that the feature could not be inspected and an assumption has been made based on the property's age and type.

Feature	Description	Rating
Wall	Cavity wall, as built, insulated (assumed)	Good
Window	Fully double glazed	Average
Main heating	Electric storage heaters	Average
Main heating control	Automatic charge control	Average
Hot water	Electric immersion, off-peak	Average
Lighting	Low energy lighting in 57% of fixed outlets	Good
Roof	(another dwelling above)	N/A
Floor	Solid, limited insulation (assumed)	N/A
Secondary heating	Room heaters, electric	N/A

# Primary energy use

The primary energy use for this property per year is 355 kilowatt hours per square metre (kWh/m2).

## What is primary energy use?

#### **Environmental impact of this property**

One of the biggest contributors to climate change is carbon dioxide (CO2). The energy used for heating, lighting and power in our homes produces over a quarter of the UK's CO2 emissions.

# An average household produces

6 tonnes of CO2

### This property produces

4.6 tonnes of CO2

# This property's potential production

4.3 tonnes of CO2

By making the <u>recommended changes</u>, you could reduce this property's CO2 emissions by 0.3 tonnes per year. This will help to protect the environment.

Environmental impact ratings are based on assumptions about average occupancy and energy use. They may not reflect how energy is consumed by the people living at the property.

### How to improve this property's energy performance

Making any of the recommended changes will improve this property's energy efficiency.

If you make all of the recommended changes, this will improve the property's energy rating and score from D (67) to C (69).

What is an energy rating?

# Recommendation 1: Low energy lighting

Low energy lighting

## Typical installation cost

£30

Potential energy

rating

### Typical yearly saving

£20

# Potential rating after carrying out recommendation 1

67 | D

# Recommendation 2: High performance external doors

High performance external doors

### Typical installation cost

£1,000

### Typical yearly saving

£33

# Potential rating after carrying out recommendations 1 and 2

69 | C

# Recommendation 3: Floor insulation (solid floor)

Floor insulation (solid floor)

## Typical installation cost

£4,000 - £6,000

## Typical yearly saving

£50

# Potential rating after carrying out recommendations 1 to 3

71 | C

# Recommendation 4: Change heating to gas condensing boiler

Gas condensing boiler

Typical installation cost

£3,000 - £7,000

Typical yearly saving

£253

Potential rating after carrying out recommendations 1 to 4



# Paying for energy improvements

Find energy grants and ways to save energy in your home. (https://www.gov.uk/improve-energy-efficiency)

Estimated energy use and potential savings

Estimated yearly energy cost for this property

£882

Potential saving

£53

The estimated cost shows how much the average household would spend in this property for heating, lighting and hot water. It is not based on how energy is used by the people living at the property.

The estimated saving is based on making all of the recommendations in how to improve this property's energy performance.

# Heating use in this property

Heating a property usually makes up the majority of energy costs.

# Potential energy savings by installing insulation

The assessor did not find any opportunities to save energy by installing insulation in this property.

Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

# **Assessor contact details**

### Assessor's name

**Dermot McGladery** 

### **Telephone**

07703 495777

### **Email**

dermotmcgladery@hotmail.com

# Accreditation scheme contact details

https://find-energy-certificate.digital.communities.gov.uk/energy-certificate/0139-3996-0209-7808-2934

### **Accreditation scheme**

Elmhurst Energy Systems Ltd

### **Assessor ID**

EES/005938

### Telephone

01455 883 250

#### **Email**

enquiries@elmhurstenergy.co.uk

# **Assessment details**

#### Assessor's declaration

No related party

#### Date of assessment

7 November 2018

#### **Date of certificate**

### 7 November 2018

### Type of assessment



► RdSAP

### Other certificates for this property

If you are aware of previous certificates for this property and they are not listed here, please contact us at <a href="mailto:mhclg.digital-services@communities.gov.uk">mhclg.digital-services@communities.gov.uk</a> or call our helpdesk on 020 3829 0748.

There are no related certificates for this property.